

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	y to constitute a va	ilid maintenance p	ermit. This permit r	nust be complete	
prior to perfo	orming maintenance activi	ties and remain or	-site for the durat	ion of the maintenar	nce activity.	
Date of Maintenance		n for Maintenance:	0		2	
Property Address:	2321 18th St Co	urt N	Property Owner's N	lame: Jim Ba	ymolomeu	
Municipality: <u>Lake</u>	ELMO ZIP: 550					
	No: 19609011157				 wer Service/ L167	
				100 00 00 00 00 00 00 00 00 00 00 00 00		
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
$\square$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintena	ance Hole Other (e	enter authorization co	ode)		
2. Were all covers se	ecurely replaced? Yes	□ No ↓	o dpep			
	of tank leakage from a se	,		tank below the oper	ating depth or	
evidence of dam	aged, cracked, or structur	ally unsound main	tenance hole cove	rs? Yes No	ating depth of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes Mo	☐ Yes ☐ No	Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed					
Tank #1 500	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other	concerns.	
-						
6. Location of septage	e disposal: St. pa	9)				
			Lange Contract			
	Pinky'	s Environmental Se	wer Service Inc.			
		PO Box 35	1			

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.