

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance act	ety to constitute a v	alid maintenance	permit. This permit r	nust be completed	
prior to performing maintenance act		^		nce activity.	
Date of Maintenance: 6 6 Reas	son for Maintenance:	Rou	tine		
Property Address: 1605 87th St	S	Property Owner's I	Name: Jue Sk	'ow	
Municipality: <u>Hastings</u> zip: <u>5</u>	5033 Property Ide				
- 121 1			ky's Environmental Se	wor Coming / 14472	
3		<u>- 1111</u>	ky s Liiviioiiiiieiitat Se	wer Service/ L16/3	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped	The second secon	Liquid Level of Tank — in			
\square Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurement	ts) = % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Mainte	nance Hole Other			3.000	
2. Were all covers securely replaced? \(\subseteq \text{ Ye}		flower 9			
	3 110 177	riower 9	91947		
3. Is there evidence of tank leakage from a s	eptic, holding, pret	reatment or pump	tank below the opera	ating depth or	
evidence of damaged, cracked, or struct	urally unsound mair	itenance hole cove	ers? Yes No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☑ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove	ed?				
Tank #1 500 gal Tank #2	gal Pretreatment	tank g	al Pump Tank	ادم	
5. Other information: List any troubleshooting	g, minor repairs cor	nducted, tank safe	ty concerns or other	gat	
	in the second of the second	and sure	cy concerns, or other	concerns.	
	The state of the s				
5. Location of septage disposal: St. Pa	41	The Paris			
				7	
Pink	y's Environmental Se	wor Consider Inc.			
	PO Box 35				
	FO DOX 33	4			

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.