

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a va	lid maintenance pe	ermit. This permit	must be completed
<u>prior</u> to perfo	rming maintenance activitie	es and remain on	-site for the durati	on of the maintena	nce activity.
Date of Maintenance:	6-5-18 Reason f	or Maintenance:	Partine		
Property Address:	875 Inwood A	KN.	Property Owner's Na	ame: Roa Ma	ucDonales
	eEmo ZIP: 550				
Maintenance Permit N	26/11611126				ewer Service/ L1673
		antennet Hame at	id Electise No. 1 lins	3 Liviloninentat se	wer service/ L16/3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	n <b>ove septage:</b> $\square$ Maintenand	ce Hole Other (e	enter authorization co	de)	
	curely replaced?  Yes				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? $\square$ Yes $\square$ No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 <u>/ 500</u>	_ gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal
	List any troubleshooting, r				
Tunk in land	escaping under bishe	2			
( ) anting of a set	P				
o. Location of septage	disposal:				
*	N		A 3		
	Pinky's	Environmental Se	wer Service Inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.