

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	y to constitute a v	alid maintenance p	ermit. This permit r	nust be completed	
prior to performing maintenance activ			tion of the maintenar	nce activity.	
Date of Maintenance: 6-5-18 Reason					
Property Address: 2367 North 810	lge gre CIL	Property Owner's N	lame: Bruce	Marrause	
Municipality: Stillwate ZIP: SS	SZ Property Ide	entification Number	:		
Maintenance Permit No: <u>V 0971511182</u>	Maintainer Name a	nd License No. Pink	xv's Environmental Sev	wer Service/ I 1673	
			, s = morning near se	Wel Selvicer E1075	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank ——— in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintena	ance Hole Other (
2. Were all covers securely replaced? Yes			,		
3. Is there evidence of tank leakage from a se	ptic, holding, pret	reatment or pump	tank below the oner	ating denth or	
evidence of damaged, cracked, or structur	ally unsound mair	tenance hole cove	ers? Yes No	acting depth of	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	Yes Wo	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1 /500 gal Tank #2 /000	_gal Pretreatmen	tankg	al Pump Tank	gal	
Other information: List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or other	concerns.	
cable line runing over top of	munhole				
		171			
6. Location of septage disposal:					
Pinky	's Environmental Se	ewer Service Inc.			
	PO Box 35	4			

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.