

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety t	o constitute a valid	d maintenance per	mit. This permit m	ust be completed
	ming maintenance activitie			n of the maintenanc	ce activity.
Date of Maintenance:	6-5-18 Reason f	or Maintenance: _	Routine		4
Property Address: 43	10 mc Donald	On No Pr	operty Owner's Na	me: Benton	tree
Municipality: Stelle	water ZIRSSO8	Property Ident	tification Number:		
Maintenance Permit No	::05744V 10107M	aintainer Name and	d License No. Pinky	's Environmental Sew	ver Service/ L1673
Maintenance Permit No	J. 001 1 101 101				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ———— in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3 Is there evidence	curely replaced? Yes of tank leakage from a sepaged, cracked, or structure	tic, holding, pretr	9 rden eatment or pump t tenance hole cove	rs? L Yes L No	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1500	gal Tank #2 1000	_gal Pretreatmen	t tankg nducted, tank safe	al Pump Tankety concerns, or oth	gal er concerns.
6. Location of septag	ge disposal: St. Pal	1			
	Pink	y's Environmental S	sewer Service Inc.		
	, ,,,,,	PO Box 3			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673