

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	to constitute a v	alid maintenance r	permit. This permit r	must be completed	
<u>prior</u> to perfo	orming maintenance activi	ties and remain or	n-site for the dura	tion of the maintena	nos activity	
	6-5-18 Reason			tion of the maintenan	ice activity.	
	- 1 - 1	for Maintenance:		DWING		
Property Address: $\frac{2}{}$	) SLAKE Thou t	Tu .	Property Owner's N	Name: Inthi	du Anderson	
Municipality: Lak	ZIP:	Property Ide	entification Number	~•		
Maintenance Permit 1	No: CO945K1174					
	<u></u>	Manicamer Name a	nd License No. Pink	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in				
$\square$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	move septage:   Maintena	nce Hole Other (				
2. Were all covers se	ecurely replaced?  Yes	□ No		40/1/2)		
	of tank leakage from a sep		reatment or nump	tank holow the ones	-ti dth	
evidence of dame	aged, cracked, or structur	ally unsound main	tenance hole cove	ers? Yes No	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?	,				
Tank #1/230	gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or other	concerns.	
6. Location of septage	disposal:	al .	100			
	Pinky's	s Environmental Se	wer Service Inc.			
		DO Boy 25	4			

PO Box 354

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.