

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	id maintenance p	ermit. This permit	must be completed
prior to perfor	ming maintenance activit	ies and remain on	site for the durat	ion of the maintena	nce activity.
Date of Maintenance:	5-17-18 Reason	for Maintenance:	Cout	100	
Property Address: 95	543 57th She	et North	roperty Owner's N	ame: (1/0 a	tale
Municipality: Lake		2 Property Iden			o Carce
	11000 101-0				
Maintenance Permit N	o: <u>anssel0109</u> 1	Maintainer Name ar	d License No. <u>Pink</u>	y's Environmental Se	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers sec Is there evidence of 	curely replaced? Maintena furely replaced? Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, pretr	eatment or pump	tank below the oper	,)
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 />>>	gal Tank #2 / >>>	_gal Pretreatment	tankga	al Pump Tank	gal
	List any troubleshooting,				
6. Location of septage	disposal: St. M				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673