

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
prior to perfor	ming maintenance activit	ies and remain on-	site for the duration	on of the maintenance	e activity.	
Date of Maintenance:	5 - 16 - 18 Reason	for Maintenance: _	Routi	ne		
Property Address: 13	690 Paragon t	Ne N P	roperty Owner's Na	me: Karen Sa	honebau	
Municipality: Still	vater zip:550	82 Property Iden	tification Number:			
Maintenance Permit N	0:00051110974	Maintainer Name an	d License No. Pinky	's Environmental Sew	er Service/ L167	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)	
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if	no provide measurements	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintena	ance Hole Other (e	nter authorization co	de)		
	curely replaced? Yes					
	of tank leakage from a se		eatment or pump	tank below the opera	ating depth or	
	aged, cracked, or structu					
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	d?				
Tank #1 _/500	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ty concerns, or othe	r concerns.	
700 old fe	- numbole per how	m. amer				
6. Location of septag	e disposal:					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673