

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

System Location				
Address 1852 Harro	w Ave.	Telephone Number	651-755-3	3261
City Forest lake State MPZIP S30 Stroperty ID No./GEO Code				
Owner Kevin Wick	Pumping Date 4/2	0/16		*
Control of the Contro	Contractor		A State of the second s	
Maintainer Boss Pumping	MPCA License No. 1945	Telephone Number	(651) 466-0800	
What was done to the system?		Report Liquid Capacity in	Gallons	
Tank(s) Pumped	Tank 1: 12	OD Pumped Tank 2:	1200 Pumped	
Sludge and scum measured.  Do tanks need to be pumped?	9 arjk 3: 5	DPumped Tank 4:	Pumped	
Yes No (If no provide measurements b	pelow) Total Gallons	Pumped: 2900	_	
Visual Inspection (note any problems with the system): NOTE: This does not serve as a compliance inspection.				
			CEIVED	
*		M	1AY 12 2016	
c7262d1464		PUBL	IC HEALTH	
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped				
Tank Length in. <b>X</b> Tank Width in. <b>X</b> Tank Depth in. = Tank Volume (cubic inches)				
Tank Radius in. X Tank Radius in. X 3.14 = Tank Volume (cubic inches)				
Tank Volume (cu. in.) / 231.01 = Liquid Capacity Gallons / Tank Depth in. = Gallons/Inch				
Sludge Level in. <b>X</b> Gallons Per Inch	= Sludge Volume	Gallons		
Scum Level in. X Gallons Per Inch = Scum Volume Gallons				
Sludge Volume + Scum Volume	= Total Sludge and Scum V	olume Gallons	.	
Total Sludge and Scum Volume / Liquid Capacity = Percent Sludge and Scum in Tank %				
		*Tanks must be pun following condition:		
Scum Layer		12 inches from the b	oottom of the outlet	
Effluent	Tank Depth measur from invert of outle		scum volume is greater	
- Cludes I ave	pipe to bottom of ta	than 25 marsant of t		
Sludge Layer	pasaranautan			
Signature A A	Data ///	11/6 [	Reset Form	
Signature	Date 4-0		react Fulfil	