

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entiret	y to constitute a v	alid maintenance ¡	permit. This permit r	must be complete	
prior to per	forming maintenance activ	rities and remain o	n-site for the dura	tion of the maintenar	nce activity.	
Date of Maintenanc	e: $\overline{23/-1}$ Reaso	n for Maintenance:	Routine			
Property Address: _	12345 Anola	Ta No.	Property Owner's 1	Name: Glenn	Detara	
Municipality: <u>St</u>	2	292 Property Ide			- Caron	
Maintenance Permit	No: 54007 011305					
		manifed Hame a	nd License No. Filli	ky's Environmental Se	wer Service/ L167	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
\square Sludge and scum measured		III	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Maintena	ance Hole Other	enter authorization -		1 23% of greater	
2. Were all covers s	ecurely replaced? Yes			ode)		
			e old			
evidence of dan	e of tank leakage from a se naged, cracked, or structur	ptic, holding, preti	reatment or pump	tank below the opera	ating depth or	
The state of the s		ally unsound main	tenance hole cove	ers? L Yes W No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	s of septage were removed	?				
Tank #1 600	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	gal	
 Other information 	n: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other	concerns	
				, , , , , , , , , , , , , , , , , , , ,	concerns.	
. Location of septag	e disposal: St. Pag	1				
		/				
	Pinky'	s Environmental Se	wer Service Inc.			
		PO Box 35	4			

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.