

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to performing maintenance activit	ies and remain o	n-site for the durat	ion of the maintena	nce activity.	
	for Maintenance:	1	re	,	
Property Address: 140 Lake Elmo	Ne N	Property Owner's N	lame: Todd \$1	Dis Wittmen	
		entification Number		our vymmer	
			y's Environmental Se	ewer Service/ L1673	
9				2,0,0	
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
$\square$ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
<ol> <li>Were all covers securely replaced? Yes No Not Aug up</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No</li> </ol> Tank Leaking Out Leaking In Cover Damage					
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☑ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?  Tank #1 gal Tank #2  5. Other information: List any troubleshooting,	gal Pretreatmen	tankga	ıl Pump Tank	gal	
6. Location of septage disposal: <u>Sナ. Pay</u>					
PO Box 354					

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673