

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be | e completed in its entirety | to constitute a v | alid maintenance | permit This permit | |
|-----------------------------|-----------------------------|--|------------------------|-----------------------|---------------------|
| prior to perfo | rming maintenance activit | ies and remain o | n-site for the dura | tion of the maintant | must be completed |
| Date of Maintenance: | 7-23-18 Reason | for Maintenance: | Reune | on or the maintena | ince activity. |
| Property Address: | O(1) | | Property Owner's N | Name: Polly | Hen |
| Municipality: _S_ | Watu ZIP: 55 | | entification Number | | 1100 |
| Maintenance Permit N | 10-0- | | | | |
| | 0 | Tanic a | nd License No. Pili | ky's Environmental Se | ewer Service/ L1673 |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank — in | | | |
| ☐ Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if | no provide measurements) | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to rem | nove septage: Maintenan | ice Hole Other (| enter authorization co | ode) | 3.000 |
| | curely replaced? Yes | | | , | |
| | of tank leakage from a sept | | eatment or nump | tank halam th | |
| evidence of dama | ged, cracked, or structura | Ily unsound main | tenance hole cove | rs? Ves No | ating depth or |
| | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐No | ☐ Yes ☐ No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | of septage were removed? | | | | |
| | gal Tank #2 1000 | gal Pretreatment | tankga | l Pump Tank | gal |
| 5. Other information: | List any troubleshooting, r | minor repairs con | ducted, tank safet | y concerns, or other | concerns |
| 1/2 | | | | | |
| | | | | | |
| . Location of septage | disposal: | | | 8 | |
| | | | | | |
| | Pinky's | Environmental Sev | wer Service Inc. | | |
| | | | | | |

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001