

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

I i	completed in its entirety t				
Date of Maintenance:	2 2 10	for Maintenance:			,
Property Address: 1	5051 70° SA	n Sc	Property Owner's Na	me: NUN	Melson
Municipality: HUS	trop zip: 550	33 Property Ide	ntification Number:		
Maintenance Permit N	0: <u>091288+11732</u> M				ewer Service/ I 1673
				5 Elivinoimientat 5	the servicer Elore
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b	pe pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if i	Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or gr				if 25% or greater
1. Access used to rem	ove septage: Maintenan	ce Hole Other (e	enter authorization co	de) To Ol	6
	curely replaced? Yes				
3. Is there evidence of	of tank leakage from a sept	ic, holding, pretr	eatment or pump t	ank below the ope	rating depth or
	ged, cracked, or structura			The second secon	3
	Tank	Leaking Out	Leaking In	Cover Damage	•
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1000 gal Tank #2gal Pretreatment tankgal				l Pump Tank	gal
	List any troubleshooting,				
			114		
		01			
6. Location of septage	disposal:SL/	mil	-		
	Pinky's	Environmental Se	wer Service Inc		
	i iilky 3	PO Box 35			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001 P: 651-439-4847 License Number: L1673