

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	ho completed !- '				Harree Ferrini	
prior to pe	be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	t must be complet	
	maniteriance acti	vities and remain o	n-site for the dura	tion of the mainten	ance activity.	
Date of Maintenan	ce: <u>7-19-18</u> Reas	on for Maintenance:	Routine			
Property Address:	488 Julep Am	e No.	Property Owner's I	Name: Our	Selve	
Municipality: La	Le Elno ZIP: 55	042 Property Ide	entification Number	8	Full	
Maintenance Permi	it No: <u>N9431M11292</u>	Maintainer Name a	nd License No. Birl			
		Traine o	na License No. Pili	ky s Environmental S	ewer Service/ L16	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to r	remove septage: Mainten			mast be pumped	or greater	
			enter authorization co	ode)		
3. Is there oxidens	securely replaced? Yes	L No				
evidence of day	e of tank leakage from a se	eptic, holding, preti	eatment or pump	tank below the ope	rating depth or	
or deliver of du	maged, cracked, or structu	rally unsound main	tenance hole cove	rs? 🗌 Yes 🗌 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallon	s of septage were removed		65 _ 110	les lino		
	Tank #1 gal Tank #2 gal Pretreatment tank gal		I Down To I			
5. Other information: List any troubleshooting, minor repairs conducted, tank safety			rump rank	gal		
System in	Rock garden	, milor repairs con	ducted, tank safet	y concerns, or othe	r concerns.	
6. Location of septag	ge disposal:					
		4				
	Pinky ¹	's Environmental Sev	ver Service Inc			
	,	PO Box 354				
		1 O DOX 332				

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.