

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This						
This section must be	e completed in its entiret	y to constitute a v	alid maintenance p	permit. This permit	must be complet	
prior to perio	maintenance activi	ities and remain o	n-site for the dura	tion of the mainten	ance activity	
Date of Maintenance:	7-17-18 Reason	n for Maintenance:	Routine		and delivity.	
Property Address:	1460 30t St.			Name: Mama	1 lee	
Municipality: After	ZIP: 550		entification Number			
Maintenance Permit N	10. L7288 × 11377	Maintainen				
	lo: <u>L7288 x 11327</u>	maiitainer Name a	nd License No. Pink	ky's Environmental S	ewer Service/ L16	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
\square Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintena	ince Hole Other (enter authorization co	ode)		
	curely replaced? Yes			,		
3. Is there evidence	of tank leakage from a sec	otic, holding pret	reatment or numn	tank halam th		
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No						
	Tank			163 🗀 160		
	0.2.01.00.01.00	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of	of septage were removed?	,				
Tank #1 75 D	gal Tank #2 /250	gal Pretreatment	tankga	l Pump Tank	gal	
. other information.	List any troubleshooting,	minor repairs con	ducted, tank safet	V concerns or othe	r concerns	
System too	del for mun ho	le e		•		
. Location of septage	disposal:					
	Pinky's	Environmental Se	wer Service Inc.			
		PO Box 354	1			

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.