

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must h	ne completed in its anti-st		200		mance Perilli	
prior to perf	oe completed in its entiret	y to constitute a v	alid maintenance	permit. This perm	it must be complet	
Date of Maintenance	forming maintenance activ	icies and remain o	on-site for the dur	ation of the mainter	nance activity.	
Date of Maintenance	e: <u>7-13-18</u> Reason	n for Maintenance:	Keutin	Q		
Property Address:	HSI Hilltop A	re N.	Property Owner's	Name: TIME	Mazzanes	
Municipality:	eEmo zip:550	47 Property Id	entification Number		maccares	
Maintenance Permit	No: t 15050 11320	Maintain and		er:		
	No: <u>t1505c11320</u>	Maintainer Name a	and License No. <u>Pir</u>	ky's Environmental	Sewer Service/ L16	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured		11				
Do tanks need to be pumped?		Sludge + Scum	Sludge Level in Tank in Scum Level in Tank in			
☐ Yes ☐ No (if no provide measurements)			Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater.			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					d if 25% or greater	
			enter authorization o	code)		
2. Were all covers se	ecurely replaced? Yes	□ No				
ovidence of dam	of tank leakage from a sep	itic, holding, pret	reatment or pump	tank below the ope	erating depth or	
evidence or dam	aged, cracked, or structur	ally unsound main	tenance hole cove	ers? 🗌 Yes 🗌 No	3	
	Tank	Leaking Out	Leaking In	Cover Damage	-	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed?				<u>-</u>	
Tank #1 /500	gal Tank #2	gal Pretreatment	tank g:	al Pump Tank		
Other information:	List any troubleshooting,	minor repairs con	ducted tank safe	ty conserve	gal	
to old to	manhale per hou	me Oleman	adeced, talk sale	ty concerns, or other	er concerns.	
6. Location of septage	disposal:					
	Pinky's	Environmental Sev	wer Service Inc.			
		PO Box 354				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001