Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	t be completed in its entire	aty to constitut				
prior to pe	t be completed in its entire	vities and remain o	alid maintenance	permit. This permi	it must be complet	
Date of Maintenan	ce: <u>7-13-18</u> Reas	on for Maintenance	Zentin a	ation of the mainter	nance activity.	
Property Address:				The	. 7	
Municipality: ()	.11 -10-1	10-		Name: Thoma	W KOGIN	
			entification Numbe	er:		
maniferiance Fermi	it No: <u>0</u> 657441477	Maintainer Name a	nd License No. <u>Pir</u>	ıky's Environmental S	Sewer Service/ L167	
Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		11	Sludge Level in Tank ——— in Saura Laura			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level 11 Tank in			
☐ Yes ☐ No (if no provide measurements)		11	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to r	emove septage: Mainter	nance Hole Other (enter authorization	rode)	20% of greater	
2. Were all covers	securely replaced? Yes	. □ No	addionization (.ode)		
3. Is there evidence	e of tank leakage from a se	eptic, holding, preti	eatment or nump	tank helevist		
evidence of da	maged, cracked, or structu	rally unsound main	tenance hole cove	ers? Yes No	erating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage	-	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallon	s of septage were removed	1?				
Tank #1 /500	gal Tank #2	_gal Pretreatment	tankg	al Pump Tank	nal.	
or other informatio	iii. List any troubleshooting	, minor repairs con	ducted, tank safe	ty concerns or othe		
System to	dup to expose in	markele		-,	er concerns.	
a Location of Septas	ge disposal:					
	Piliky	's Environmental Sev PO Box 354				

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.