

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be complete	
prior to per	rforming maintenance activ	ities and remain o	n-site for the dura	tion of the mainten	ance activity.	
Date of Maintenand	ce: <u>7-10-18</u> Reason	on for Maintenance:	Routine			
Property Address:	8802 Carle Jone	T/1. No.	Property Owner's	Name: Report	Vathland	
Municipality: (CE EIMO ZIP: 55	OY7 Property Ide	entification Number	Name. POTOCTT	Faman	
Maintenance Permi	t No 3205 VIV 15	Maintain N		r:		
The state of the s	t No:p3205×11615	Maintainer Name a	ind License No. Pin	ky's Environmental S	ewer Service/ L167	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		II .	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to r	emove septage: Mainten	ance Hole 1 Ofher (11 25% of greater	
	securely replaced? \(\simega\) Yes		enter authorization c	ode)		
evidence of dar	e of tank leakage from a se maged, cracked, or structu	rally unsound main	tenance hale seve	tank below the ope	rating depth or	
		any unsound main	terialice flote cove	ers!		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes □ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallon	s of septage were removed	!?				
Tank #1 _750	gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	gal	
o. Other informatio	n: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other	r concerns	
System to	90 old for manhold	5			· concerns.	
b. Location of septag	ge disposal:					
	D:1	1. F	7 11 100 100 100 1000			
	Pinky	's Environmental Se	wer Service Inc.			

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.