Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	v to constitute	-1:-1	The District		
This section must be completed in its entiret	itios and remain	alid maintenance	permit. This permi	t must be complete	
<u>prior</u> to performing maintenance activ	n for Maintenance:	Reutin	2		
Property Address: 16845 1087	St. NC.	Property Owner's	Name: \(\O\n\)	Diller	
Municipality: Syllycto ZIP: 550	Property Ide	entification Number		HILL	
Maintenance Permit No C 1957 v 11743	roperty la	entification Numbe	r:		
Maintenance Permit No: 91957 r 11243	Maintainer Name a	and License No. <u>Pin</u>	ky's Environmental S	ewer Service/ L167	
Maintenance Performed	Tank Mea	surement (must b	e completed if tank	s NOT numped)	
Tank(s) Pumped Liquid Level of Tank — ir				re i pampeu)	
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintena	ince Hole Other (enter authorization c	ode)	3, 00.00	
2. Were all covers securely replaced? Yes		flower			
3. Is there evidence of tank leakage from a sep	otic, holding, pret	reatment or nump	C791Gen		
evidence of damaged, cracked, or structur	ally unsound main	tenance hole cove	ers? Yes No	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No				
	□ Tes ☑ No	Yes No	☐ Yes ☐No		
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?	?				
Tank #1 Sec gal Tank #2	_gal Pretreatment	tankg	al Pump Tank	as l	
Other information: List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or othe	er concerns	
			,,	. Concerns.	
5. Location of septage disposal: 52. pg.	7		- T		
			1		
Pinky's	Fnvironmental So	wer Service Inc			

Maintenance activities must be reported to the Department within 90 days.

PO Box 354 Afton MN 55001