

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perfo	orming maintenance activiti	ies and remain o	n-site for the durati	on of the maintena	nust be completed
Date of Maintenance	1 1 117	for Maintenance:		tine	nce activity.
Property Address: 14040 30th St. So Property Owner's Name: Lisa Stanley					
Municipality:	zip: <u>550</u>	Property Id	entification Number:		agrass
Maintenance Permit	40: <u>16991m11066</u> m	aintainer Name a	and License No. Pinka	's Environmental Ca	
			and License No. I liky	3 Livironinentat Se	wer Service/ L1673
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & So		ks must be pumped	
1. Access used to rer	nove septage: Maintenand	ce Hole Other	enter authorization cod	(a) Keeklee	1 25% of greater
2. Were all covers se	curely replaced? Yes	No	authorization coo	C) TI BAK ON	en sida walk
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
Tes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	of septage were removed?				
Tank #1 15 🔊	gal Tank #2g	gal Pretreatment	t tankgal	Pump Tank	aal
5. Other information:	List any troubleshooting, n	ninor repairs cor	nducted, tank safety	concerns or other	gat
	1	•	,	concerns, or other	concerns.
(E.)					
. Location of septage	disposal: 5th	/			
Pinky's Environmental Sewer Service Inc.					
	and the state of t	PO Box 35			
		Afton MN 55			
		com mil JJ	001		

Maintenance activities must be reported to the Department within 90 days.