DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730



SSTS MAINTENANCE REPORT

Date of Maintenance 12-4-15 Reason to	or Maintenance: Ro	whic		
Property Address: 10460 Gray Class			WHILL /Kim Hener	ricks
Municipality: College grove	State MN Zip Code	55016 GEO CO	de/Property I.D. #:	
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured.	Liquid Level of Tank	Liquid Level of Tank in. Sludge Level in. Scum Level in.		
Do tanks need to be pumped? Yes No (If no provide measurement)	Total (Sludge + Scu	m)/ Liquid Lev	rel = % Sludge & Scum	*
1. Access used to remove septage: Mainten	ance Hole Cother (C	Go to #3 below)	 Tank must be pumped if this is greater than 25%. 	value
2. If maintenance hole was used, were all covers	securely replaced?	Yes No please exp	lain	
Explanation:				
3. If owner refuses to allow a Subsurface Sew them complete and sign the following state	age Treatment Systen ement:	n (SSTS) to be pumped t	through the maintenance noie, r	ave
I, (or) hole. I understand that removal of solids and			ds and liquids through the mainte dered maintenance.	nance
4. Is the tank designed as a leaky tank? example.				
		, , , , , , , , , , , , , , , , , , , ,		
Tank#1 Yes No Verificatio Method	Used:			
Tank#2 Yes No Verificatio Method				
5. Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound	eptic, holding, pretrea d maintenance hole co	tment or pump tank be vers?	low the operating depth or evid	ence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes 📉 No	☐ Yes ☐ Mo	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were remov	ed?			
Tank #1 1760 Tank #2 Pretreatment Tank Pump Tank				
7. Other information: List any troubleshooti	ng, minor repairs cond	ducted, tank safety con	cerns, or other concerns.	
8. Certification: I hereby certify as a State of Mand made the observations, Maintainer's Name: SCHLOMKA SERVICES L	or directly supervised o	thers in the performance	nally conducted the work of this job. nd St S, Hastings MN 55033	
	ainer's Phone #: 651-4.			
Maintainer's Signature			17/4/15	