

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

				of the manifeman	
Date of Maintenance: 1	Reason fo	or Maintenance: _	ZM.		
Property Address:	528 Slst Street	MONT P	roperty Owner's Na	ime: Steve Sma	lex
A 4 4 4	ZIP:				
Maintenance Permit No	: N4917K 31111 ME	aintainer Name an	d License No. Olsor	n's Sewer Service/L2	16
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? \(\sumsymbol{\infty} \) Yes \(\sumsymbol{\infty} \) No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	□ Yes ŪNo	☐ Yes ☐ No	
	Septic/Holding Tank #2	□ Yes □ Qo	☐ Yes ☐Mo	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1 (1W)	of septage were removed?	gal Pretreatmen	t tank g	al Pump Tank	gal
Tank #1 1 (1W)	of septage were removed?	gal Pretreatmen	t tank g	al Pump Tank	gal er concerns.
Tank #1 1 (1W)	of septage were removed?	gal Pretreatmen	t tank g	al Pump Tank	gal er concerns.
Tank #1 1 (1W)	of septage were removed? gal Tank #2 (100) List any troubleshooting,	gal Pretreatmen	t tank g	al Pump Tank	gal er concerns.

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082

Maintenance activities must be reported to the Department within 90 days.