DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance Reason for Maintenance: Rowne				
Property Address: 7294 Grane Da Ave S Property Owner's Name: Jory Rosga				
Municipality: Corres Grove State MN Zip Code 55016 GEO Code/Property I.D. #:				
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Yes ☐ No (If no provide measurements)	Liquid Level of Tank in. Sludge Level in. Scum Level in. Total (Sludge + Scum) / Liquid Level = % Sludge & Scum *			
* Tank must be pumped if this value is greater than 25%.				
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain				
Explanation:				
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement: I,				
damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes F×No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	Yes No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank Yes No				
Tank #1 1000 Tank #2 1000 Pretreatment Tank Pump Tank 7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
8. Certification: I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintainer's Name: SCHLOMKA SERVICES LLC. Maintainer's Address: 13450 122nd St S, Hastings MN 55033				
Maintainer's License #: 2989 Maintainer's Phone #: 651-459-3718				
Maintainer's Signature Date: 11-20-15				