DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11 -19-15 Reason for I	Maintenance: <u>A</u>	owne		
Property Address: 5616 Garoen	Proper	ty Owner's Name:	was Sites	
Municipality: Woodbury St	ate MN Zip Code	Siza GEO Code	e/Property I.D. #:	
What was done to the system?	hat was done to the system? Tank Measurements (nust be completed if tanks NOT pumped)	
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Yes No (If no provide measurements)	Liquid Level of Tanl Total (Sludge + Scu		= % Sludge & Scum*	
* Tank must be pumped if this value is greater than 25%.				
2. If maintenance hole was used, were all covers se	ecurely replaced?	Yes No please explai	in	
Explanation:				
hole. I understand that removal of solids and lice 4. Is the tank designed as a leaky tank? example: see Tank#1	nent: der's name), refuse to quids through other a gepage pit, cesspool, do sed: sed: sed: sed:	allow the removal of solids ccess points is not conside rywell, leaching pit	s and liquids through the maintenance ered maintenance.	
Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed	Comm.	Samuel Samuel	National Control of the Control of t	
Tank #1 \ 750 Tank #2 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
8. Certification: I hereby certify as a State of Minand made the observations, or Maintainer's Name: SCHLOMKA SERVICES LLC	directly supervised o	Maintainer that I personal thers in the performance o ner's Address: 13450 122nd	r this job.	
mantaner strainer				
Maintainer's License #: 2989 Maintair	ner's Phone #: 651-4	 59-3718		