

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

				ion of the mantenan	ice activity.
	2 von 18 Reason 1				
Property Address: 23	490 OWERLD AVE	N	Property Owner's N	ame: Matt Com	resck
Municipality: Scare	ZIP: 550	Property Ide	ntification Number	:	
Maintenance Permit N	0: <u>CO257g 14142</u> M	aintainer Name a	nd License No. Smil	ie's Sewer Service/L2	.428
	~				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenan	ce Hole X Other	enter authorization co	ode)	
3. Is there evidence of	orrely replaced? A Yes of tank leakage from a sepaged, cracked, or structura	tic, holding, pret ally unsound mair	tenance hole cove	ers? 🗌 Yes 风 No	ating depth or
		Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🖾 No	☐ Yes 🔼 No	☐ Yes 🏻 No	
	Septic/Holding Tank #2	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1	of septage were removed? gal Tank #2 : List any troubleshooting,	gal Pretreatmen	t tank g nducted, tank safe	al Pump Tank ety concerns, or othe	gal gal r concerns.
6. Location of septage	e disposal: Land A	001:00			

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934