

SSTS MAINTENANCE REPORT

System Location

Address 9340 north shore tr Telephone Number (651) 464-5832
 City Forest Lake State mn ZIP 55025 Property ID No./GEO Code
 Owner Jo Anne House Pumping Date Nov 13, 2018

Contractor

Maintainer Row Sewer Service MPCA License No. L3309 Telephone Number (651) 464-5505

What was done to the system?

Tank(s) Pumped
 Sludge and scum measured.
 Do tanks need to be pumped?
 Yes No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1,250 Pumped Tank 2: 1,000 Pumped
 Tank 3: Pumped Tank 4: Pumped
 Total Gallons Pumped: 1,250

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.


RECEIVED

NOV 26 2018

DEPARTMENT OF PUBLIC HEALTH

*Tank Measurements Use Only if Tank(s) Were NOT Pumped

Tank Length _____ in. Tank Width _____ in. Tank Depth _____ in. = Tank Volume (cubic inches) _____
 Tank Radius _____ in. Tank Radius _____ in. 3.14 = Tank Volume (cubic inches) _____
 Tank Volume (cu. in.) _____ / 231.01 = Liquid Capacity _____ Gallons / Tank Depth _____ in. = Gallons/Inch _____
 Sludge Level _____ in. Gallons Per Inch _____ = Sludge Volume _____ Gallons
 Scum Level _____ in. Gallons Per Inch _____ = Scum Volume _____ Gallons
 Sludge Volume _____ + Scum Volume _____ = Total Sludge and Scum Volume _____ Gallons
 Total Sludge and Scum Volume _____ / Liquid Capacity _____ = Percent Sludge and Scum in Tank _____ %



Tank Depth measured from invert of outlet pipe to bottom of tank

*Tanks must be pumped if either of the following conditions exist:
 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Signature [Handwritten Signature]

Date Nov 13, 2018

Reset Form