

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

prior to perior	ming maintenance activit	ies and remain on	-site for the durati	on of the maintena	ince activity.
Date of Maintenance: _		for Maintenance:	Res Maint		
Property Address: 13616 195th St. N Property Owner's Name: Tury Lawrence					
Municipality: Marineo	NSt. COIL ZIP: 5500				
	027797014451 A				_2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
 ☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Majntena	nce Hole Other (e	enter authorization co	ode)	
 Were all covers securely replaced? Yes □ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? □ Yes □ No 					
¥	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes → No	☐ Yes ► No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1200 5. Other information:	of septage were removed gal Tank #2 List any troubleshooting	_ gal Pretreatmen			
6. Location of septage	e disposal: Land L	(b) (:24)			2

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934