



Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9-29-18 Reason	for Maintenance:			
Property Address:	9775 235+L St.	N	Property Owner's N	lame: John (ulsan
Municipality: Fosca	Lake ZIP: SSO2	S Property Ide	entification Number	:	
	0:47/36n/3099 M				216
			The Election No. Oto	on a sever service, E	210
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped □ Sludge and scum measured		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if r		rains made be pumped if 25% of greater			
1. Access used to rem	nove septage: 🗹 Maintenan	ce Hole 🗌 Other (enter authorization c	ode)	
 2. Were all covers securely replaced? Yes □ No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? □ Yes ▼ No 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes 🗹 No	
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1_1125	of septage were removed? gal Tank #2 425 List any troubleshooting,	gal Pretreatmen minor repairs co	t tank g nducted, tank safe	al Pump Tank ty concerns, or oth	gal er concerns.

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082

Maintenance activities must be reported to the Department within 90 days.