

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

| | -14/01 | | | | | |
|---|--|--|--|-------------------------------------|---------------------|--|
| Date of Maintenance: | 8/18/8 Reason | for Maintenance: | | | | |
| Property Address: 100 Tanglewood Lane Property Owner's Name: Ken Dobson | | | | | | |
| Municipality: Mari | | | | | ē. | |
| Maintenance Permit N | 10: <u>K5635X12640</u> A | | | | 216 | |
| | | Tomico Traine a | TO EIGENSE NO. Oth | DIT 3 SEWEL SELVICE/L | 210 | |
| | | | | 72.00 | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | | |
| ☐ Tank(s) Pumped ☐ Sludge and scum measured | | Liquid Level of Tank in | | | | |
| | | 11 | Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 | | | |
| Do tanks need to | • | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | | |
| ☐ Yes ☐ No (if | no provide measurements) | | Sicute | | | |
| 1. Access used to ren | n ove septage: Maintenar | nce Hole 🔲 Other (| enter authorization c | ode) | | |
| | curely replaced? | | | , | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or | | | | | | |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes W No | | | | | | |
| | Tank | | | | Í | |
| | | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☑ No | Yes No | ☐ Yes ☐ No | | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| Tank #1_11_5 5. Other information: | of septage were removed? gal Tank #2 List any troubleshooting, | gal Pretreatment | t tank g nducted, tank safe | al Pump Tank ty concerns, or oth | gal er concerns. | |
| Location of septage | disposal: Metra | | | | | |

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082