DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730



SSTS MAINTENANCE REPORT

Date of Maintenance 10/22/19 Reason for Maintenance: Rowting			
Property Address: 9770 Millitery RU Property Owner's Name: Paul Kot Nowr Municipality: Cottosc grove State MN Zip Code 55016 GEO Code/Property I.D. #:			
Municipality: Cottosc grove State MN Zip Code 55016 GEO Code/Property I.D. #:			
What was done to the system? Tank Measurements (must be completed if tanks NOT pumpe			eted if tanks NOT pumped)
▼ Tank(s) Pumped	Liquid Level of Tank in. Sludge Level in. Scum Level in.		
Sludge and scum measured.	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum *		
Do tanks need to be pumped?			
Yes No (If no provide measurements)	JL L F Other/Co.	to #3 holow)	* Tank must be pumped if this value
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) is greater than 25%.			
2. If maintenance hole was used, were all covers securely replaced? No please explain			
Explanation:			
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have			
them complete and sign the following statement:			
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 Yes Verificatio Method Used:			
The Marificatio Mothod Used:			
Tank#2 Yes No Verificatio Method Used: 5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of			
5. Is there evidence of tank leakage from a septic, holding, pretieating to pump tank below the open as a septic, holding, pretieating to pump tank below the open as a septic, holding, pretieating to pump tank below the open as a septic, holding, pretieating to pump tank below the open as a septic, holding, pretieating tank below the open as a septic, and the open as a septic, holding, pretieating tank below the open as a septic, and the open as a septic, and the open as a septic of the open as a septic o			
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	☐ Yes XNo	☐ Yes ☐ No	Yes No
Septic/Holding Tank #2		☐ Yes ►No	☐ Yes ☐ No
Pretreatment Tank	☐ Yes ☐ No	Yes No	Yes No
Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No
6. How many gallons of septage were removed?			
Tank #1 \(\frac{1}{2} \) Tank #2	Pretreatment Tank Pump Tank		
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.			
8. Certification: Thereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work			
and made the observations, or directly supervised others in the performance of this job.			
Maintainer's Name: SCHLOMKA SERVICES LLC. Maintainer's Address: 8890 202nd St. N Forest Lake, MN 55025			
Maintainer's License #: 2989 Maintainer's Phone #: 651-459-3718			
Maintainer's Signature Date: 16/22/15			