

RECEIVED

SSTS MAINTENANCE REPORT

PUBLIC HEALTH

System Location		
Address	20640 Keewah'tin Ave	Telephone Number
City	Forest Lake	State MN ZIP 55025 Property ID No./GEO Code
Owner	Kerry Voiss	Pumping Date 5/18/18
Contractor		
Maintainer	DT Septic Services	MPCA License No. #3663 Telephone Number (763) 286-1815

What was done to the system?

Tank(s) Pumped

Sludge and scum measured.

Do tanks need to be pumped?

Yes No (If no provide measurements below)

Report Liquid Capacity in Gallons

Tank 1: 1200 Pumped Tank 2: Pumped

Tank 3: Pumped Tank 4: Pumped

Total Gallons Pumped: 1200

Visual Inspection (note any problems with the system):

NOTE: This does not serve as a compliance inspection.


j95φ8615φ91

***Tank Measurements-Use Only if Tank(s) Were NOT Pumped**

Liquid Level of Tank (Distance from invert of outlet pipe to bottom of tank) _____ in.

Sludge Level _____ in. + Scum Level _____ in. = Total Sludge and Scum Level _____

Total Sludge and Scum Level _____ / Liquid Level _____ = Percent Sludge and Scum in Tank _____ %



Liquid Level measured from invert of outlet pipe to bottom of tank

*Tanks must be pumped if either of the following conditions exist:
 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or
 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Signature _____

Date _____

Reset Form

pd
2d-county
entirely