

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety i				
Date of Maintenance:	8-30-18 Reason	for Maintenance:	Routine		
Property Address: <u>5</u>	323 Stillunter	Blulb	Property Owner's Na	ame: Mike of Ma	ny Tuesnen
Municipality: Stell	water ZIP:500	Property Ide	ntification Number:		
Maintenance Permit N	0: 98026d12060 M	aintainer Name ar	nd License No. Pinky	r's Environmental Sev	wer Service/ L167
	9				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ———— in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? Yes [of tank leakage from a septence of ta septence of tank leakage from a septence of tank leakage from a	tic, holding, pretr		The second secon	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 /5000	of septage were removed? _ gal Tank #2 List any troubleshooting,	gal Pretreatment			
	to expose man hate				
6. Location of septage	disposal:				
	Pinky's	Environmental Se	ewer Service Inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.