

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	oe completed in its anti-		se meatment	system Mainte	enance Permit	
prior to perf	oe completed in its entiret forming maintenance activ	y to constitute a	valid maintenance	permit. This permi	it must be completed	
	(2 10)	reies and remain	on-site for the dura	tion of the mainter	nance activity.	
- The state of the	Reaso	n for Maintenance	:	ITIME		
Property Address:	0684 104 \$1	A No.	Property Owner's N	Jame: Oud	. /	
Municipality:	Elno ZIP:550	542 Property Id	dentification Number	guay 6	al ser	
Maintenance Permit	No: 23894 g 12040	Maintainer Name	and License No. Divi			
	J	The state of the s	and License No. Pink	y's Environmental S	ewer Service/ L1673	
Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped ☐ Sludge and scum measured		Liquid Level o	Liquid Level of Tank — in			
Do tanks need to be pumped?		Studge Level II	Sludge Level in Tank in Scum Level in Tank in			
	no provide measurements)		Sludge + Scum / Liquid Level X 100			
			cum Tai	nks must be pumped	if 25% or greater	
. Access used to rer	move septage: Maintena	nce fole Other	enter authorization co	de) minhal	· Louis	
60161336	carety replaced: Yes	No		11111		
3. Is there evidence	of tank leakage from a sep	tic, holding, pret	reatment or nump			
evidence of dama	aged, cracked, or structura	ally unsound mair	ntenance hole cover	s? Yes No	rating depth or	
	Tank	Leaking Out				
	Septic/Holding Tank #1		Leaking In	Cover Damage		
		Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons o	of septage were removed?			The state of the s		
Tank #1 1500	gal Tank #2	gal Pretreatment	tank gal	Dump Tank		
Other information:	List any troubleshooting, I	minor repairs cor	ducted tank safety	Pullip Tank	gal	
			iddeted, talk safety	concerns, or othe	r concerns.	
		1				
Location of septage of	disposal:					
	Pinky's	Environmental Se	wer Service Inc.			
		PO Box 354				
		Afton MN 550	001			
	P: 651-4	39-4847 Liconso	Number: L1673			
	1.031 4.	LICEIISE	Mullipel. L10/3			

Maintenance activities must be reported to the Department within 90 days.