

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be co	ompleted in its entirety to	o constitute a val	id maintenance per	rmit. This permit r	nust be completed
prior to perform	ing maintenance activitie	es and remain on-	site for the duration	on of the maintena	nce activity.
Date of Maintenance:	8127/18 Reason fo	or Maintenance: _	Routine		
Property Address:	80 Quinla	Ave. S. P	roperty Owner's Na	me: Dennis	Doerr
Municipality: Lake	Ichel zip: 55cm	Property Ider	tification Number:		
	x920d12830M				wer Service/ L1673
	6				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	rely replaced? Yes tank leakage from a septed, cracked, or structural	ic, holding, pretr			rating depth or
_	Tank	Leaking Out	Leaking In	Cover Damage	
5	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
5	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
ı	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
I	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
100	f septage were removed?				
ACCOUNT AND		gal Pretreatment			gal
5. Other information: I	List any troubleshooting, in the stank	Contraction of the Contraction o	aducted, tank safety	The second secon	er concerns.
,					
6. Location of septage of	disposal:			A TOTAL CONTRACTOR	
	Pinky's	Environmental Se	wer Service Inc.		
		DO D 05			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673

Maintenance activities must be reported to the Department within 90 days.