

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must I	be completed in its entiret	v to constitute a v	alid maintenance	pormit This		
prior to per	forming maintenance activ	ities and remain o	n-site for the dura	tion of the maintain	must be completed	
Date of Maintenance	e: 18 Reaso	n for Maintenance:	Routine.	ctori or the maintena	nce activity.	
Property Address:	520 Kimbro 1			Name: Pam Ku	kaika	
Municipality: Cotto	age Grove ZIP:	Property Ide	entification Numbe	r:		
Maintenance Permit	No: <u>m3888812494</u>	Maintainer Name a	and License No. Pin	ky's Environmental Co		
			2.cense 110. <u>1 111</u>	ky 3 Environmentat Se	wer Service/ L16/3	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured		II .	Sludge Level in Tank			
Do tanks need to be pumped?			Student Communication			
☐ Yes ☐ No (if no provide measurements)						
			= % Sludge & Scum Tanks must be pumped if 25% or greater Hole Other (enter authorization code)			
		1 /	1	ode)		
	ecurely replaced? Yes		deep			
Is there evidence	of tank leakage from a sep	otic, holding, pret	reatment or pump	tank below the opera	ating depth or	
evidence of dam	naged, cracked, or structur	ally unsound mair	tenance hole cove	ers? Yes No	acing depen of	
	Tank	Leaking Out				
		Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed:	?				
Tank #1 12 S			tank	I Down To 1		
	: List any troubleshooting,	minor repairs	dust du l	al Pump Tank	gal	
	a management of the second of	minor repairs cor	iducted, tank safe	ty concerns, or other	concerns.	
. Location of septage	e disposal: 52. pa	41				
	uisposuii					
	Pinlad	. Environmental C	4			
	FIIIKY :	S Environmental Se				
		PO Box 35				
		Afton MN 55	001			

Maintenance activities must be reported to the Department within 90 days.