

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	he completed in its anti-					
prior to per	be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be complete	
Prior to per	Torming maintenance activ	ities and remain o	n-site for the dura	ation of the maintena	ance activity.	
Date of Maintenance	e: 5/16/18 Reaso	on for Maintenance:	Keesti			
Property Address:	7975 Kombro F	ne No.	Property Owner's	Name: Keeth	Nort	
Municipality:	Munter ZIP:55	Property Ide	entification Numbe	or.		
Maintenance Permit	NO COLCAHZILACS	Maintaines				
	No: Clausingus	Maintainer Name a	and License No. Pir	iky's Environmental Se	ewer Service/ L167	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped			Liquid Level of Tank ——— in			
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to		Sludge + Scum				
☐ Yes ☐ No (i	f no provide measurements) = % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	emove septage: Mainten	ance Hole Other (enter authorization	codo)	3. 64.61	
2. Were all covers s	ecurely replaced? Yes	□ No.	addion Edition	iode)		
3. Is there evidence	of tank leakage from a se	ptic, holding pret	reatment or nume	damle bullet 1		
evidence of dam	naged, cracked, or structu	rally unsound main	tenance hole cover	ers? Vos Who	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1	gal Tank #2 150	_gal Pretreatment	tankg	al Pump Tank	gal	
5. Other information	: List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or other	Concerns	
	00 occ fe	r man	nela	, , , , , , , , , , , , , , , , , , , ,	concerns.	
		S C II				
. Location of septage	e disposal:					
				III.		
	Pinky'	s Environmental Se	wer Service Inc.			
		PO Box 354	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001