## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section mus	it be completed in its entire	ty to constitute a	alid maintenance	pormit This		
	citorining maintenance acti	vities and remain o	n-site for the dur	tion of the maintain	must be complete	
Date of Maintenar	nce: 1/10 Reas	on for Maintenance	Kartin			
Property Address:	11508 1157 St	NC.	7 -011100	T0-55		
Municipality: St	7/11 (17( 71) S		Property Owner's	Name: Cresco	Steschen	
At : .	Muato ZIP: S	C Property Id	entification Numbe	r:		
Maintenance Perm	nit No: 5/094111590	Maintainer Name	and License No. Pin	ky's Environmental Se	ewer Service/ L167	
	enance Performed					
			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum			
$\square$ Yes $\square$ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to	remove septage:   Mainten	ance Hole Other	enter authorization c	ode)		
2. Were all covers	securely replaced? Yes	DNO flo	wers arew	dit		
3. Is there evidend	ce of tank leakage from a se	entic holding pret	reatment or num-	tool by the		
evidence of da	amaged, cracked, or structu	rally unsound mair	tenance hole cove	tank below the oper	rating depth or	
			The Hote Cove			
	Tank 	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallor	ns of septage were removed	1?		The second secon		
Tank #1 1500	gal Tank #2	gal Pretreatment	tank	A Dump Taul		
. Other information	on: List any troubleshooting	minor repairs cor	ducted tank and	Tump rank	gal	
	,	, milor repairs cor	iducted, tank sare	ty concerns, or other	r concerns.	
. Location of septa	ge disposal: SZ. PG4	. 1				
	7					
	. Pinky	's Environmental Se	wer Service Inc			
		PO Box 35				
		Afton MN 550				

Maintenance activities must be reported to the Department within 90 days.