Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This saction	v 8					
This section must be	completed in its entirety	to constitute a	alid maintenance	permit. This permi	t must be completed	
<u>prior</u> to perfo	rming maintenance activi	ties and remain o	n-site for the dura	tion of the mainter	ance activity	
Date of Maintenance:		for Maintenance		tine	direct delivity.	
Property Address: 1	5320 113th St	No	Property Owner's I	Name: Great 1	Viane Kram	
Municipality: Stal	Lwater ZIP:550		entification Number		(
Maintenance Permit N	10: +4220U12004	Maintainer Name a	and License No. Pink	ky's Environmental S	Sewer Service/ L1673	
No. of the last of		NAME OF THE PARTY				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		II .	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintena	nce Hole Clother				
			enter authorization co	ode) Wodge	Coverconni	
	curely replaced? Yes			set D	4	
ouidence o	of tank leakage from a sep	tic, holding, pret	reatment or pump	tank below the ope	rating depth or	
evidence of dama	ged, cracked, or structura	ally unsound mair	itenance hole cove	rs? 🗌 Yes 🗖 No		
	Tank	Leaking Out	Leaking In	Cover Damage	•	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed?					
Tank #1 15 00	gal Tank #2	gal Pretreatment	tank ga	Pump Tank	an!	
6. Other information:	List any troubleshooting,	minor repairs cor	ducted tank safet	V concerns an att	gal	
	37		idacted, talk salet	y concerns, or other	er concerns.	
		1				
. Location of septage	disposal.	/				
	1940					
	Pinky's	Environmental Se	wer Service Inc.			
PO Box 354						

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001