

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be seemed to the				- Crimic	
This section must be completed in its entiret	y to constitute a	valid maintenance	permit. This permit	must be completed	
to performing maintenance activ	ities and remain o	on-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance: 8-9-18 Reason	n for Maintenance			,	
Property Address: 9150 Consing +	tre. le	Property Owner's N	Name: Vni M	eglitsch	
Municipality: St. Wato zip: 50	87 Property Id	entification Number	:		
Maintenance Permit No: 47822812249					
	Trainer Hame	and License No. Pink	xy's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Me	asurement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured Sludge Level in Tank in Scum Level in Tank				i	
Do tanks need to be pumped?	be pumped? Sludge + Scum / Liquid Level × 100				
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or great					
1. Access used to remove septage: Maintena	nce Hole Other	(enter authorization		11 25% of greater	
2. Were all covers securely replaced? Yes		deriter authorization co	ode)		
3. Is there evidence of tank leakage from a con-	□ NO				
Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structure	ally unsound main	reatment or pump	tank below the oper	ating depth or	
	any unsound mair	itenance hole cove	rs?		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	Yes Ho	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?			-		
Tank #1 / gal Tank #2	gal Pretreatment	t tank ga	Pump Tank	~~!	
. Other information: List any troubleshooting,	minor repairs cor	nducted, tank safet	V COncorns or other	gat	
System too old for manhote			y concerns, or other	concerns.	
. Location of septage disposal:					
			8		
Pinky's	Environmental Se	wer Service Inc.			

PO Box 354

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.