

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b				The control of the co		
prior to perf	oe completed in its entirety	to constitute a	alid maintenance	permit. This permit	must be completed	
Prior to peri	orning maintenance activity	ties and remain o	n-site for the dura	ation of the maintena	ance activity.	
Date of Maintenance		for Maintenance:				
Property Address:	13830 ZIST S	1 \$6	Property Owner's	Name: Bruce -	Fontaine	
Municipality:	Mwater ZIP5508	Property Id	entification Numbe	r:		
Maintenance Permit	No: K3643m12036	Maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service / L1673	
					THE SELVICE E1075	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintenar			mast be pumped	11 23% of greater	
2 11/	maintenar			ode)		
2. Were all covers se	ecurely replaced? Ves [No to	deep			
3. Is there evidence	of tank leakage from a sep	tic, holding, pret	reatment or numn	tank below the oper	ating depth or	
evidence of dam	aged, cracked, or structura	ally unsound mair	ntenance hole cove	ers? 🗌 Yes 🔼 No	depen of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☐No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed?					
Tank #1 15 00	_gal Tank #2 _lecc	gal Pretreatment	tank ga	A Dump Tank		
. Other information	: List any troubleshooting,	minor repairs ser	dusted to all so	rump rank	gal	
	, a castesitoching,	minor repairs cor	iducted, tank safet	ty concerns, or other	concerns.	
. Location of septage	disposal: 5+ PCI	1				
- Le dation of Septage	disposat.					
	Pinkv's	Environmental Se	wor Sonden Inc			
	y 3	PO Box 35				
		PI RAV JE	1			

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.