

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety prior to performing maintenance activities				-
Date of Maintenance: 9/19/18 Reason	for Maintenance:	Reutine		
Property Address: 4950 Susper	Ave	Property Owner's N	ame: David	Many John
Municipality: Lake (mo zIP: 558)	42 Property Ide	ntification Number:		_
Maintenance Permit No: 4100 Z 1003 M	aintainer Name a	nd License No. Pink	y's Environmental Sev	wer Service/ L167
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
☑ Tank(s) Pumped	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a septential evidence of damaged, cracked, or structural evidence. 	tic, holding, preti			ating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed? Tank #1 gal Tank #2		t tank ga	al Pump Tank	gal
5. Other information: List any troubleshooting,				
mennele 4+				
6. Location of septage disposal:				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673