Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance r	ormit This		
<u>prior</u> to perfo	rming maintenance activit	ties and remain or	-site for the dura	tion of the maintenant	nust be completed	
Date of Maintenance:		for Maintenance:		tion of the maintena	nce activity.	
Property Address: <u>S</u>	49 Stillucito	RILL, W	Property Owner's N	Name: MM/	OPNOID	
Municipality: Still	MUTU ZIP: 556	2 Property Ide				
Maintenance Permit N	0:25962413487 A				 wer Service/ L1673	
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ——— in				
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
Yes No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to rem 	ove septage: Maintenar	nce Hole 🖰 Other (e	nter authorization co	ode)		
	urely replaced? Yes					
Is there evidence o	f tank leakage from a sep	tic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
evidence of dama	ged, cracked, or structura	ally unsound maint	enance hole cove	ers? 🗌 Yes 🕖 No	acing depth of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
S-	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	f septage were removed?					
Tank #1	gal Tank #2	gal Pretreatment	tankga	l Pump Tank	gal	
. Other information:	List any troubleshooting,	minor repairs con	ducted, tank safet	ty concerns, or other	concerns.	
	0.10					
. Location of septage of	disposal: 1 fa	91				
	Pinky's	Environmental Sev	ver Service Inc.			
		PO Box 354				

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001