## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance	10 - F-15 Reason for	Maintenance: RC	utine		
Property Address: 13	313 St. Chuix T	1. Mc Proper	ty Owner's Name:	KU Svang	
Municipality: Still	wenter s	tate My Zip Code	55087 GEO Code	e/Property I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped  Sludge and scum measured.  Do tanks need to be pumped?  Yes No (If no provide measurements)		Liquid Level of Tank  Total (Sludge + Scu		= % Sludge & Scun	
1. Access used to remo	ve septage: Maintena	nce Hole	io to #3 below)	* Tank must be pumped if the is greater than 25%.	his value
2. If maintenance hole	was used, were all covers s	ecurely replaced?	Yes No please expla		
Explanation:					
3. If owner refuses to	allow a Subsurface Sewag sign the following staten		(SSTS) to be pumped th	rough the maintenance hole	e, have
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand t	hat removal of solids and lie	quids through other a	ccess points is not conside	ered maintenance.	
<b>4.</b> Is the tank designed	as a leaky tank? example: so	eepage pit, cesspool, dr	ywell, leaching pit		
Tank#1  Yes  No Verificatio Method Used:					
Tank#2 T Yes T	No Verificatio Method U	Ised:			20
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
Sep	tic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐ No	
Sep	tic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pre	treatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pur	np Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons	of septage were removed	d?			
Tank #1 1500	Tank #2	Pretreatment Tank Pur		mp Tank	
7. Other information	: List any troubleshooting	g, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
8. Certification: The and	reby certify as a State of Mir made the observations, or	directly supervised ot	hers in the performance o	f this job.	
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001					
Maintainer's Licens	e #: 1673 Maintair	ner's Phone #: 651-43	9-4847		
Maintainer's Signat	urd does	V	Date: /	0-8-15	