
## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 





## **SSTS MAINTENANCE REPORT**

	or Maintenance:	Lourne		
Property Address: 12312 Men	DOW blust Proper	ty Owner's Name:	an Hens	
Municipality: AFton	State My Zip Code	200	le/Property I.D. #:	_
What was done to the system?	Tank Meas	Tank Measurements (must be completed if tanks NOT pumped)		
<ul><li>☐ Tank(s) Pumped</li><li>☐ Sludge and scum measured.</li><li>Do tanks need to be pumped?</li><li>☐ Yes</li><li>☐ No (If no provide measurement)</li></ul>	Liquid Level of Tank ts) Total (Sludge + Scu		el = % Sludge & Scum	n. *
1. Access used to remove septage: Mainte	nance Hole	Go to #3 below)	<ul> <li>Tank must be pumped if this vails greater than 25%.</li> </ul>	ue
2. If maintenance hole was used, were all cover				
Explanation:				
3. If owner refuses to allow a Subsurface Sew them complete and sign the following state	ement:		hrough the maintenance hole, hav Is and liquids through the maintenar	
l, (o hole. I understand that removal of solids and				
4. Is the tank designed as a leaky tank? example				
Tank#2 Yes XNo Verificatio Metho				
E Is there evidence of tank leakage from a s	antic halding pretres	tur and ay mumm tank ha		•
damaged cracked or structurally unsoun	d maintenance hole co	vers?	ow the operating depth or eviden	ce of
damaged, cracked, or structurally unsoun	d maintenance hole co	vers?  Leaking In	Cover Damage	ce of
damaged, cracked, or structurally unsoun  Tank  Septic/Holding Tank #1	d maintenance hole co	vers?		ce of
damaged, cracked, or structurally unsoun  Tank	d maintenance hole co Leaking Out	vers? Leaking In	Cover Damage	ce of
damaged, cracked, or structurally unsoun  Tank  Septic/Holding Tank #1	d maintenance hole co Leaking Out Yes	Leaking In Yes Mo	Cover Damage  Yes No	ce of
damaged, cracked, or structurally unsoun  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2	Leaking Out  Yes No  Yes No	Leaking In Yes No Yes No	Cover Damage  Yes No Yes Mo	ce of
damaged, cracked, or structurally unsoun  Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank	Leaking Out  Yes No  Yes No  Yes No  Yes No	Leaking In  Yes No  Yes No  Yes No	Cover Damage  Yes No  Yes No  Yes No	ce of
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	d maintenance hole co	Leaking In  Yes No  Yes No  Yes No  Yes No	Cover Damage  Yes No  Yes No  Yes No	ce of
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  6. How many gallons of septage were removed.	d maintenance hole co  Leaking Out  Yes No  Yes No  Yes No  Yes No  Pretreatment T	Leaking In  Yes No  Yes No  Yes No  Yes No  Yes No	Cover Damage  Yes No Yes No Yes No Yes No Yes No	ce of
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  6. How many gallons of septage were removed and the observations, and made the observations, and ma	Leaking Out  Yes No Yes No Yes No Yes No Yes No Wed?  Pretreatment To ing, minor repairs cond Minnesota certified SSTS or directly supervised or	Leaking In  Yes No  Yes No  Yes No  Yes No  Yes No  Ank  Aucted, tank safety conditions in the performance	Cover Damage  Yes No Yes No Yes No Yes No Yes No And Yes No  White the work of this job.	ce of
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  6. How many gallons of septage were removed as a State of and made the observations,  Maintainer's Name: SCHLOMKA SERVICES I	Leaking Out  Yes No Yes No Yes No Yes No Yes Sono Yes Son	Leaking In  Yes No  Yes No  Yes No  Yes No  Yes No  Ank  Hucted, tank safety conditions in the performance mer's Address:  13450 122r	Cover Damage  Yes No Yes No Yes No Yes No Who And Y	ce of
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  6. How many gallons of septage were removed at the control of the contro	Leaking Out  Yes No Yes No Yes No Yes No Yes No Wed?  Pretreatment To ing, minor repairs cond Minnesota certified SSTS or directly supervised or	Leaking In  Yes No  Yes No  Yes No  Yes No  Yes No  Ank  Hucted, tank safety conditions in the performance mer's Address:  13450 122r	Cover Damage  Yes No Yes No Yes No Yes No Yes No And Yes No  White the work of this job.	ce of