

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GÖVERNMENT CENTER
14949 62nd STREET NORTH P. O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

- 144 - 144	mining manitenance activ	The second second second second second	THE RESERVE OF THE PERSON NAMED IN	tion of the mainten	ance activity.	
Date of Maintenance:		on for Maintenance:	maint.	*		
Property Address: 🐣	10010 :112+y 8	. oH.fe	Property Owner's	Name: John Mu	relles	
Municipality: \	Worant ZIP:55	N Property Ide	entification Numbe	r:		
Maintenance Permit	40: £3165 k 14704	Maintainer Name a	nd License No. Ole	an's Sewer Service/I	716	
		The state of the s	ind Elcense No. Ob	OII. 3 SEWEL SELVICE/L	240	
	the second second		Salam China		and the second second	
TELEVISION OF THE PARTY OF THE	Price Majoristan			ः रक्तानांभरपर है स्कार	Fich bulestered	
X Tank(s) Rumped			Liquid Level of Tank h			
Sludge and soum	neasured	Studge 4 Soum	Studge Level in Tank in Scum Level in Tank, in Studge + Scum / Liquid Level X 100			
Do tanks need to		I w O/ Selection in the selection	um Ta	inks must be pumped	if 25% or greater	
——————————————————————————————————————	no provide measurements					
l. Access used to rei	move septage: Mainten	ance Hole Other (enter authorization c	ođe)		
	curely replaced? V Yes				ž	
3. Is there evidence	of tank leakage from a se	eptic, holding, pret	reatment or pump	tank below the ope	rating depth or	
evidence of dam	aged, cracked, or structu	rally unsound main	tenance hole cove	ers? Yes No		
	Tank	Leaking Out	Leaking In	Cover Damage	*	
2	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☑No		
	Septic/Holding Tank #2	Yes No	☐ Yes MNo	☐ Yes ☒No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	192025				
Tank #11050	_ gal Tank #2 <u>D50</u>	_ gal Pretreatment	tank ga	al Pump Tank	gal	
5. Other information	: List any troubleshooting	g, minor repairs cor	nducted, tank safe	ty concerns, or othe	r concerns.	
-						
. Location of septage	e disposal: St Raw	1 mater				
	-1,1000	- have				

Olson's Sewer Service Inc 17638 Lyons St NE Forest Lake, MN 55025 License# 216 P: 651-464-2082