

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a v	alid maintenance	permit This permit	must be seemed to	
prior to performing maintenance acti	vities and remain o	n-site for the dura	tion of the maintena	nust be completed	
Date of Maintenance: 12-25-17 Reas	on for Maintenance:	Ratine	tion of the maintena	ice activity.	
Property Address: 14786 Aften 1	Blue. Sc	Property Owner's N	Name: Irean F	treneus	
Municipality: TRY ZIP: 55	of the last of the	entification Number			
Maintenance Permit No: 3 670 f 14812	Maintainer Name				
101118	Maintainer Name a	nd License No. Pink	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of Tank — in				
☐ Sludge and scum measured	II Scall Level III falk				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
Yes No (if no provide measurement	s) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: $\square$ Mainter	nance Hole Other				
<ol> <li>Were all covers securely replaced?  Yes</li> <li>Is there evidence of tank leakage from a see evidence of damaged, cracked, or structure.</li> </ol> Tank	eptic, holding, preti	reatment or pump tenance hole cove Leaking In	tank below the operators?  Yes No Cover Damage	ating depth or	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No			
			☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank  Pump Tank	☐ Yes ☐ No		☐ Yes ☐ No		
Pump Tank  4. How many gallons of septage were remove	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank  4. How many gallons of septage were removed  Tank #1/ b > gal Tank #2	☐ Yes ☐ No  d? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	gal	
	☐ Yes ☐ No  d? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	gal concerns.	
Pump Tank  4. How many gallons of septage were removed  Tank #1/ b > gal Tank #2	☐ Yes ☐ No  d? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	gal concerns.	
Pump Tank  4. How many gallons of septage were removed  Tank #1/  gal  Tank #2  5. Other information: List any troubleshooting	☐ Yes ☐ No  d? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	gal concerns.	
Pump Tank  4. How many gallons of septage were removed  Tank #1/ b > gal Tank #2	☐ Yes ☐ No  d? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No tankga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank	gal concerns.	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673