## **Pumping Report**

<b>Sewer Service</b>	s Inc.		Lic: 2502			_	
Date Serviced: 6-8-18 Driver: Zxx					Type: Residential 1 Commercial		
	,					Industrial	intercial
Scheduled Maintenance: Emergency Services:					Start time: Stop time:		
Address: 9028	KIME	RA AVE					
Name: KRIS AND LIZ MYHRE  Address: 9028 KIMBRO AVE  Did you measure the accumulation of scum and sludge?					City: GROVE  No, pumped regardless		
						No, pampea i	egaruless
	Tank 1	Tank 2	Tank 3	Tank 4	Pretreat	ment	Pump Tank
Gallons Billed	1,000	1,000					Tump rank
Scum							
Sludge							
% full		-					
Operating Depth							
Access used	MH	MH					
Depth to lid	AG	AG-					
		· · · · · · · · · · · · · · · · · · ·					
		, refuse to	allow the re	moval of the so	olids and lig	uids through	
the maintenance hol	e. I understa	nd that remo	val of solids	and liquids the	rough other	access	
points is not consider							
removal requirement					oc idiilii cii	c solids	
Owner's Signature:			6				
Tank Type - Preca	t - Block -	Concrete	- Plastic -	Other			
Filter: Yes		Type of sy	stem:	RAVITY	Ton	cl	
Type of waste: Rou	mestic - H	olding - Co	mmercial	- Industrial -	Flammah	le waste tran	
Are tanks operating	g at designe	ed depth? <b>V</b> e	No.	maastrar	Hammas	ie waste trap	
Did you observe se				- surface?	Voc		
Pump Size:			condition:		, 163,		
Are all of the cover	s securely r			7.71			
Safety concerns: /		epiacea.	.9/ 140,				
Disposal site: W	Torre						
Next recommended	d numning.	7 150	DC.	Other :			
TOXET COOMMENT	a puriping.	ZYEAR		Other:			
Comments:							
Comments,							
		The state of the s					
		THE RESERVE THE PARTY OF THE PA			+ + + + + + + + + + + + + + + + + + + +		
Sauce	Comuicas III	- 25640.0	0041-01				
sewer:	services in	c. 25648 2	outh Stree	et - Belle Pla	ine, MN 5	6011 - 952-873-	3292