

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	o completed in it.					
prior to perfe	e completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed	
prior to perior	orming maintenance activi	ties and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	: <u>2-18-19</u> Reason	for Maintenance:	Ratine			
Property Address:	1.	Ma	Property Owner's N	Name:Steve S	Chrisoler	
Municipality: <u>M</u>	ntomeeli zip: 551	S Property Id	entification Number	r:		
Maintenance Permit I	No: LO718113192	Waintainer Name				
		name a	ind License No. Pink	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if	no provide measurements)	11	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rer	nove septage: Maintenar		William Control of the Control of th	is must be pumped	ii 23% or greater	
	curely replaced? Yes		enter authorization co	ode)		
evidence of dam:	of tank leakage from a sep	tic, holding, pret	reatment or pump	tank below the oper	ating depth or	
evidence of dame	aged, cracked, or structura	ally unsound mair	tenance hole cove	ers? 🗌 Yes 🛂 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed?					
Tank #1 5 cc	gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	an!	
. Other information:	List any troubleshooting,	minor repairs cor	ducted tank safet	ty concerns or other	gal	
	3,		idacted, talk salet	ty concerns, or other	concerns.	
	6					
. Location of septage	disposal: SL. Paul		4			
	Diplovia	Environmental 5				
	FIIIKY S	Environmental Se				
		PO Box 35	4			

Maintenance activities must be reported to the Department within 90 days.

Afton MN 55001