

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be complete	
<u>prior</u> to performing maintenance acti	vities and remain o	n-site for the dura	tion of the maintena	nce activity	
Date of Maintenance: 2/15/19 Reason	on for Maintenance:	Routin	e		
Property Address: 1950 Quentir	Ave S	Property Owner's	Name: Patrica	Buck	
	5043 Property Ide				
Maintenance Permit No: 77449614180					
	- Maintenner Name a	ild Licelise No. Pill	ky s Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped	Liquid Level of	Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurement		= % Sludge & Scum Tanks must be pumped if 25% or greater ce Hole Other (enter authorization code)			
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a see evidence of damaged, cracked, or structure. 	\square No eptic, holding, preti	eatment or pump	tank below the oper	ating depth or	
Tank 	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed Tank #1 \(\colon \) gal Tank #2 \(\colon \colon \) Tank #2 \(\colon \colon \) toubleshooting	gal Pretreatment	tankgaducted, tank safe	al Pump Tank ty concerns, or other	gal concerns.	
5. Location of septage disposal: Pinky	r's Environmental Se				
Pinky	's Environmental Se	wer Service Inc.			

PO Box 354

Afton MN 55001

Maintenance activities must be reported to the Department within 90 days.