

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perfor	ming maintenance activitie	es and remain on-	site for the duration	on of the maintenar	nce activity.	
Date of Maintenance: 5/6/16 Reason for Maintenance: Kouthe						
Property Address: 8/19-80th StN Property Owner's Name: Mary Klein						
Municipality: <u>SHY</u>			Smili	e's Sewer Service		
Maintenance Permit No: 5874341124 Maintainer Name and License No P.O. Box 100						
		Scandia, MN 55073				
Maintenance Performed		Tank Measurement (mt L-3438				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
•	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gailons of septage were removed?						
Tank #1 250	gal Tank #2 250	gal Pretreatment	tankga	l Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						